2023-2025 Lead Water Testing Goodrich

	Goodrich			11///2023	re-test
Sample #	Location	Time	Result	Acceptable range Pb	
1	Upper Mens	443	1.0	≤ 5	
2	Upper Womens Left Sink	444	NOT DETECTED	≤ 5	
3	Upper Womens Right Sink	445	NOT DETECTED	≤ 5	
4	Upper Supervisors	446	2.3	≤ 5	
5	Recep. Bath	447	2.9	≤ 5	
6	Elevator Bath	448	NOT DETECTED	≤ 5	
7	Hall HR bottle filler	449	NOT DETECTED	≤ 5	
8	Hall HR fountain	449	NOT DETECTED	≤ 5	
9	1st Bath after HR	450	1.5	≤ 5	
10	2nd Bath After HR	451	1.1	≤ 5	
11	Training Room	451	1.5	≤ 5	
12	Room 132 sink	453	2.5	≤ 5	
13	Bathroom across from 135	454	NOT DETECTED	≤ 5	
14	Rm 135 sink	456	NOT DETECTED	≤ 5	
15	Room 135 bathroom sink 1st	457	NOT DETECTED	≤ 5	
16	Room 135 bathroom sink 2nd	457	2.2	≤ 5	
17	PIE room sink	458	1.1	≤ 5	
18	Data Services	500	3.1	≤ 5	
19	Room 137 storage Closet sink - not used - shutdown	502	10.0	≤ 5	3.8
20	Room 136 sink	503	2.2	≤ 5	
21	Room 136 BUB	503	2.1	≤ 5	
22	Room 136 bath	504	4.0	≤ 5	
23	Hall Bathroom by Gym	505	1.0	≤ 5	

24	hall gym bottle filler	506	NOT DETECTED	≤ 5	
25	Room 138 Back right sink	507	1.9	≤ 5	
26	Breakroom	510	3.9	≤ 5	
27	Receiving slop sink	511	4.9	≤ 5	