

**2023-2025 Lead Water Testing**  
**Maplewood main bldg**

**DATE:**

11/7/2023

Sample #	Location	Time	Result Pb	Acceptable range Pb
1	Hall sink by main entrance (2nd sink)	400	NOT DETECTED	≤ 5
2	Hall sink by main entrance (1st sink)	401	1.1	≤ 5
3	Bathrm by main door 1st sink -L	402	1.3	≤ 5
4	Bathrm by main door 2nd sink - R	402	1.7	≤ 5
5	old café in the bathroom sink	403	1.4	≤ 5
6	old café outside the bathroom sink	404	1.7	≤ 5
7	old café sink next to mini fridge	405	NOT DETECTED	≤ 5
8	old café sink next to washing machine	406	1.0	≤ 5
9	old faculty cold tap bathroom	408	NOT DETECTED	≤ 5
10	rm labeled lockerroom bathrm cold tap	412	NOT DETECTED	≤ 5
11	hall sink closest to exterior doors	413	NOT DETECTED	≤ 5
12	hall sink next to bathroom	413	NOT DETECTED	≤ 5
13	Bathroom (grade 1) 1st sink - L	414	NOT DETECTED	≤ 5
14	Bathroom (grade 1) 2nd sink - R	414	1.1	≤ 5
15	Hall sink (boys bathroom 2nd floor)	416	1.1	≤ 5
16	boys bathroom 2nd flr 1st sink -L	418	NOT DETECTED	≤ 5
17	boys bathrm 2nd flr 2nd sink - R	418	NOT DETECTED	≤ 5
18	hall by girls bathroom 1st sink - L	419	NOT DETECTED	≤ 5
19	hall by girls bathrm 2nd sink - R	419	NOT DETECTED	≤ 5
20	girls 2nd flr bathroom 1st sink - L	420	1.5	≤ 5
21	girls 2nd flr bathrm 2nd sink - R	420	NOT DETECTED	≤ 5
22	old main ofc bathroom sink	422	NOT DETECTED	≤ 5